

Triangle Technical Bulletin

Effective immediately, Triangle is making a manufacturing design modification on the 62-147 (4QK4005) and the 62-155 (4QK4003) Volvo Mack springs that are offered to customers. This is being done to match a manufacturing change made in 2004 by Hendrickson. They supply these two springs to the O.E. and aftermarket.

An attempt to offer both the old and new versions only created confusion in the marketplace, and based on an informal survey of our customers, only the newer or longer versions will be offered, matching the Hendrickson design.

Triangle Item	O.E. Number	Spring Length	Cord Length
		Measured along curve of main leaf. Center of center bolt hole to center of mounting hole	Measured straight across center of mounting hole to center of mounting hole
62-147	4QK4005	26.3125 Inches	50.375 Inches
62-155	4QK4003	26.3125 Inches	50.375 Inches